

ਦਫਤਰ: ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭਵਨ ਤੇ ਮਾਰਗ) ਸ਼ਾਖਾ, ਖੰਨਾ।

ਸੇਵਾ ਵਿਖੇ,

Principal,
British Convent School,
Village Fatehpur, Khanna, Distt. Ludhiana.

ਨੰਬਰ 467 ਮਿਤੀ 16/10/25


ਵਿਸ਼ਾ: ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਲੈਣ ਸਬੰਧੀ।

ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ ggps/2025-26/091 ਮਿਤੀ. 13.10.2025

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਵੱਲੋਂ ਦਿੱਤੇ ਗਏ ਦਸਤਾਵੇਜ਼ਾਂ ਅਨੁਸਾਰ ਉਕਤ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ **Visual** ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ ਅਤੇ ਪਾਇਆ ਗਿਆ ਹੈ ਕਿ ਨੱਥੀ ਪ੍ਰੋਫਾਰਮੇ ਦੇ **Part-II** ਵਿੱਚ ਦਰਸਾਈਆਂ ਸ਼ਰਤਾਂ ਦੇ ਅਧਾਰ ਤੇ ਉਕਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਵੇਖਣ ਨੂੰ ਸੁਰੱਖਿਅਤ ਜਾਪਦੀ ਹੈ। ਇਸ ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ ਸਕੂਲ ਦੀ ਨਵੀਂ ਬਿਲਡਿੰਗ ਹੋਣ ਕਾਰਨ ਮਿਤੀ 31.03.2029 ਤੱਕ ਜਾਂ ਜਦੋਂ ਤੱਕ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ ਖਤਮ ਨਹੀਂ ਹੁੰਦੀ (ਇਸ ਕੇਸ ਨਾਲ ਨੱਥੀ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ 14.09.2028 ਤੱਕ ਹੈ) ਉਸ ਸਮੇਂ ਤੱਕ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਆਪ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ ਖਤਮ ਹੋਣ ਤੋਂ ਪਹਿਲਾਂ ਰੀਨਿਓ ਕਰਵਾ ਕੇ, ਇਸ ਦਫਤਰ ਨੂੰ ਜਮ੍ਹਾਂ ਕਰਵਾਉਣ ਦੇ ਪਾਬੰਦ ਹੋਵੇਗੇ। ਇਹ ਸਰਟੀਫਿਕੇਟ ਆਪ ਨੂੰ ਇਸ ਸ਼ਰਤ ਤੇ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ ਜੇਕਰ ਆਪ ਵੱਲੋਂ ਉਕਤ ਸਰਟੀਫਿਕੇਟ ਲਈ ਜਮ੍ਹਾਂ ਕਰਵਾਈ ਗਈ ਫੀਸ ਵਿੱਚ ਕਿਸੇ ਵੀ ਕਿਸਮ ਦਾ ਵਾਧਾ ਹੁੰਦਾ ਹੈ ਤਾਂ ਆਪ ਉਹ ਜਮ੍ਹਾਂ ਕਰਵਾਉਣ ਦੇ ਪਾਬੰਦ ਹੋਵੇਗੇ।

ਨੱਥੀ/ PART-2

ਪਿੱਠ ਅੰਕਣ ਨੰ ਮਿਤੀ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੋ.ਨਿ.ਵਿ.
(ਭ ਤੇ ਮ) ਸ਼ਾਖਾ, ਖੰਨਾ।

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ. 2, ਲੋ.ਨਿ.ਵਿ. (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰ. 1315 ਮਿਤੀ. 13.10.2025 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜ ਕੇ ਰਿਪੋਰਟ ਕੀਤੀ ਜਾਂਦੀ ਹੈ ਕਿ ਸਕੂਲ ਵੱਲੋਂ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਰਕਮੀ 60,000/- ਰੁਪਏ, ਈ-ਚਲਾਨ ਰਸੀਦ ਨੰ. 19558271 ਮਿਤੀ 15.10.2025 ਰਾਹੀਂ Head 8782-00-102-01-00 ਅਤੇ ਰਕਮੀ 20,000/- ਰਸੀਦ ਨੰ. 17378388 ਮਿਤੀ 06.05.2025 ਰਾਹੀਂ Head 0059-80-800-85-00 ਵਿੱਚ ਜਮ੍ਹਾਂ ਕਰਵਾਈ ਗਈ ਹੈ।

ਨੱਥੀ/ PART-2

— ਸਹੀ —
ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੋ.ਨਿ.ਵਿ.
(ਭ ਤੇ ਮ) ਸ਼ਾਖਾ, ਖੰਨਾ।

(To be filled S.D.E. of PWD B&R Department)

Name of the School- British Convent School, Khanna Distt. Ludhiana

- a) JE of this office visited the above mentioned School on 05.05.2025 and have visually inspected it from all angles of safety and I find it fit for normal use as a School building.
- b) In case may addition/alteration on expansion and modification to the building is to be carried out the same be carried out under the supervisor of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is settlement of walls/foundations or caving of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
- d) The owner of the Building/Management is fully responsible regarding safety of Building from all angels in spite of this report
- e) This report is not valid for legal purpose.
- f) A separate certificate regarding Fire Fighting Should be obtained from the competent authority for every year and Submit in this Office.
- g) A separate certificate regard Electrical Works should be obtained from the competent authority
- h) The covered area of the building is 162398.25 sq. ft.
- i) As per Government order No 5/13/2018-3BR3/1294287/3 dated 10-08-2018 for issue of building safety Certificate Para 2.0 (a) This Certificate as requested by school authority is issued up to 31.03.2029 end.



Sub Divisional Engineer
Provincial Sub Division,
PWD (B&R) Khanna

